



**BS-001.22 – Boletim de Serviço –
Fluidos de operação do MC01 –
Service Bulletin -
Operating fluids of the MC01**

Rev.01
Página
1 de 2

Montaer - Montagem, Manutenção e Com. de Partes e Peças

Data da emissão /

Emission date

26/09/2022

Modelo: / Model

MC01

**Aplicabilidade: /
applicability**

Todas / All

Referências: /

References:

MANUAL DE MANUTENÇÃO (MM) Revisão 5

MANUAL DE MANUTENÇÃO (MM) Revisão 6,

PILOT'S OPERATING HANDBOOK (POH) Revisão 06

PILOT'S OPERATING HANDBOOK (POH) Revisão 07,

SI-912-016R9 Selection of suitable operating fluids for rotax Engine Type 912 i,
912 and 914 (Series)

Objetivo: / Objective:

Informar aos operados da aeronave Montaer MC01 que:

Durante a atualização dos manuais da Montaer foi detectado inconsistência com relação aos fluidos de operação da aeronave MC01 nos manuais PILOT'S OPERATING HANDBOOK (POH) revisão 06 e Manual de Manutenção (MM) revisão 05, sendo elas sanadas através da atualização dos manuais. É importante ressaltar que o fluido de freio DOT 04 não pode ser utilizado na linha de freio da aeronave MC01. As atualizações dos manuais devem ser lidas e impressas para serem adicionadas aos mesmos.

Inform operators of the Montaer MC01 aircraft that:

During the update of the Montaer manuals, an inconsistency was detected regarding the operating fluids of the MC01 aircraft in the PILOT'S OPERATING

**Av. Antônio Carneiro s/n, Bairro St. Antônio, Aeroporto, Hangar 2, Feira de
Santana - BA, CEP: 44069-010**

E-mail: engenharia@montaer.com.br

Site: www.montaer.com.br



**BS-001.22 – Boletim de Serviço –
Fluidos de operação do MC01 –
Service Bulletin -
Operating fluids of the MC01**

Rev.01
Página
2 de 2

Montaer - Montagem, Manutenção e Com. de Partes e Peças

HANDBOOK (POH) revision 06 and Maintenance Manual (MM) revision 05 manuals, which were corrected through the update of the manuals. It is important to note that DOT 04 brake fluid cannot be used in the MC01 aircraft brake line. Manual updates must be read and printed to be added to the manuals.

Assinatura

Nome do Responsável: Max Colen Corrêa

Documento do Responsável: Crea-BA 3000090467

Av. Antônio Carneiro s/n, Bairro St. Antônio, Aeroporto, Hangar 2, Feira de
Santana - BA, CEP: 44069-010

E-mail: engenharia@montaer.com.br

Site: www.montaer.com.br