



SERVICE BULLETIN ALLERT

(SBA0022025)

Important Rotax service Bulletin – Immediate Attention Required

Dear Valued Costumer,

Rotax has recently issued a Service Bulletin regarding engines 912 iS, 915 iS and 916 iS, which requires immediate attention.

While Rotax has likely already communicated this update to affected customers, we are issuing this directive to reinforce the mandatory requirement for compliance with the bulletins.

At Montaer, safety is our highest priority. We urge all owners and operators to carefully review the bulletins and take necessary action as soon as possible. Failure to comply may affect warranty coverage, aircraft airworthiness, and could lead to undesired outcomes.

Next Steps:

1. **Review the Bulletin** – You can access the full bulletin here: <https://www.rotax-owner.com/en/support-topmenu/service-bulletins>
2. **Schedule an Inspection or Service** – Contact your nearest Rotax-certified maintenance provider to ensure compliance
3. **Contact us for Assistance** – If you have any questions or require guidance, feel free to reach out to us at engenharia@montaer.com.br

Montaer strongly recommend that all users register their engines and keep their information updated with Rotax to ensure they receive important communications about safety updates and service bulletins.

Recent mandatory publications of affected engines.

Models	S/N	Bulletin
912ULS	6783108	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
	6783575	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
	6783574	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
	6783576	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines

Montaer Aeronaves

Av. Sérgio Carneiro S/N – Aeroporto Feira de Santana
Bairro Santo Antônio – Feira de Santana – BA - CEP: 44069-010 – Brasil

Cel. +55 75 99814 1207 Fixo: +55 75 3015 1207

contato@montaer.com.br



6785017	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785016	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785490	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785051	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785525	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785492	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6785491	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6786515	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
6786514	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9569814	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9569820	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9569813	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570247	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570252	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570771	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570791	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570850	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9570771	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines

Montaer Aeronaves

Av. Sérgio Carneiro S/N – Aeroporto Feira de Santana
 Bairro Santo Antônio – Feira de Santana – BA - CEP: 44069-010 – Brasil
 Cel. +55 75 99814 1207 Fixo: +55 75 3015 1207
contato@montaer.com.br



9573502	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574013	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574774	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574693	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574775	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144010	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574695	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9574694	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144032	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144416	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144011	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144012	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144030	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
9144568	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines
10000936	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines
10000940	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines

Montaer Aeronaves

Av. Sérgio Carneiro S/N – Aeroporto Feira de Santana
 Bairro Santo Antônio – Feira de Santana – BA - CEP: 44069-010 – Brasil
 Cel. +55 75 99814 1207 Fixo: +55 75 3015 1207
 contato@montaer.com.br



10000939	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p> <p>SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines</p>
10000941	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p> <p>SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines</p>
9144029	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144567	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144564	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144031	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144565	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144563	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
10001042	<p>SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines</p>
9144569	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
9144566	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>
10000938	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p> <p>SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines</p>
10000937	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p> <p>SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines</p>
10002041	<p>SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines</p>

Montaer Aeronaves

Av. Sérgio Carneiro S/N – Aeroporto Feira de Santana
 Bairro Santo Antônio – Feira de Santana – BA - CEP: 44069-010 – Brasil
 Cel. +55 75 99814 1207 Fixo: +55 75 3015 1207
contato@montaer.com.br



		SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines
	10002046	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines
	10002042	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines
	10000935	SB-912-079UL – 22/11/2024 - Essential information regarding engine installation, operation, and maintenance for ROTAX® 912 (Series) Aircraft Engines SB-912-080UL – 19/12/2024 - Inspection and/or replacement of expansion tank assy for ROTAX® 912, 914, 912 i, 915 i and 916 i (Series) Aircraft Engines

We appreciate your prompt attention to this matter and remain available to support you through the process.